

Message Text

CONFIDENTIAL

PAGE 01 MANILA 14115 160318Z
ACTION SY-05

INFO OCT-01 EA-10 ISO-00 FBOE-00 A-01 /017 W
-----103595 160606Z /21

R 160306Z AUG 78
FM AMEMBASSY MANILA
TO AMEMBASSY BANGKOK
INFO AMCONSUL HONG KONG
AMEMBASSY KUALA LUMPUR
SECSTATE WASHDC 0078

C O N F I D E N T I A L MANILA 14115

BANGKOK FOR TSO

HONG KONG FOR RTC

KUALA LUMPUR FOR RSO

WASH FOR SY/OPS/T

E.O.11652:GDS
TAGS:ASEC
SUBJECT:ACR MAINTENANCE

REF: KL 8866 (NOTAL)

1. REFTEL REPORTED PROBLEMS WITH LIGHTING IN KUALA LUMPUR
ACR AND PARENT ROOM, AND ULTIMATE NEED FOR REWIRUNG THE
ROOM LIGHTING TO SEPERATE INTERNAL LIGHTING FROM EXTER-
NAL HALLWAY LIGHTING AND REDUCE OVERLOAD OF PRESENT
CIRCUITS AND SWITCHES.

2. IN ORDER TO ESTABLISH PRIORITY AND DEFINE ULTIMATE
SCOPE OF SUCH A PROJECT, REQUEST TSO BANGKOK FURNISH
FOLLOWING INFORMATION:

A. IS THE PARENT ROOM FOILED?

CONFIDENTIAL

CONFIDENTIAL

PAGE 02 MANILA 14115 160318Z

B. WHAT IS THE POSTUTILIZATION OF THE ACR- SELDOM, WEEKLY,
ROUTINELY, ETC.?

C. NUMBER AND TYPE (4 TUBE HANGING, 2 TUBE RESTING ON ACR,
ETC.) OF FLORESCENT FIXTURES IN ROOM?

D. IS PRESENT WIRING FOR LIGHTING, A/C AND ILG IN METAL
CONDUIT? IS IT SURFACE RUN, CONCEILED IN WALLS AND CEILING
OR A MIXTURE?

E. ASSUMING, TO REDUCE CIRCUIT OVERLOAD, A SEPERATE BRANCH
WILL HAVE TO BE RUN, IS A SPARE CIRCUIT AVAILABLE IN
THAT AREAS DISTRIBUTION PANEL?

F. IS EMT, BOXES, WIRING, ETC. AVAILABLE FOR THE PROJECT?
ARE SKETCHES OF ENGINEERING PLAN AVAILABLE?

3. REGARDING REQUEST FOR SEABEE- CE,AND BU IF NECESSARY,
SHOULD BE AVAILABLE DURING AN OCTOBER/NOVEMBER TIME
FRAME.

4. IF THERE IS AN IMMEDIATE NEED FOR ACR LIGHTING, AND
REPLACEMENT FIXTURES ARE NOT LOCALLY AVAILABLE FROM
GSO, TSO TOKYO DOES HAVE SEVERAL SPARE TWO TUBE FIXTURES
THAT WERE SUPPLIED WITH BUT NOT USED IN THEIR ACRS.
THESE FIXTURES ARE THE TYPE THAT STAND ON THE CEILING
OF THE ACR. USE OF THESE FIXTURES COULD BE A TEMPORARY
FIX UNTIL REWIRING CAN BE SCHEDULED. MURPHY

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 16 aug 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978MANILA14115
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: GS
Errors: N/A
Expiration:
Film Number: D780334-1011
Format: TEL
From: MANILA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780860/aaaabxma.tel
Line Count: 79
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 64f3f662-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 04 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1727210
Secure: OPEN
Status: NATIVE
Subject: ACR MAINTENANCE
TAGS: ASEC
To: BANGKOK
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/64f3f662-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014